State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor Kathleen Clarke Executive Director

Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

Partial: XXX Complete: Exploration: Inspection Date & Time: 3/9/2000 / 9:00a.m.-3:00p.m.

Date of Last Inspection: 2/9/2000

H

Mine Name: Star Point Mine County: Carbon Permit Number: ACT/007/006						
Permittee and/or Operator's Name: Plateau Mining Corporation						
Business Address: 847 Northwest Highway 191, Helper, Utah 84526						
Type of Mining Activity: Underground XXX Surface Prep. Plant Other						
Company Official(s): Johnny Pappas						
State Officials(s): Bill Malencik Federal Official(s): None						
Weather Conditions: Snowing, 4' snow at mine site						
Existing Acreage: Permitted-9,060 Disturbed-220 Regraded-Seeded-						
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded						
Status: _Exploration/_XXX_Active/Inactive/_ Temporary Cessation/_ Bond Forfeiture						
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

<u>Instructions</u>

- . Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3. 4.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL HYDROLOGIC BALANCE:	EVALUATED [XX] []	<u>N/A</u> . ∐ ∐ ∐	COMMENTS L1 L1 L1	NOV/ENF
a. b. c. d.	DIVERSIONS SEDIMENT PONDS AND IMPOUNDMENTS OTHER SEDIMENT CONTROL MEASURES WATER MONITORING EFFLUENT LIMITATIONS	[XX] [XX] [XX] []		[XX] [XX] [XX]	
5. 6. 7. 8.	EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND	[XX] [XX]		[XX] [XX]	
10. 11. 12. 13. 14. 15.	RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS ROADS:				
a.		[XX] [XX] [XX] [XX] [_]			

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 3/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

A partial inspection was performed by the undersigned. Highlights of the inspection are as follows:

SUMMARY

- -No violations were issued as a result of the instant inspection.
- -Star Point mine had plans to move into the Hiawatha seam. There is four to five million tons of recoverable coal. This move is underway because of the uncertainties at the Willow Creek mine. This proposal is to get started after the first of the year. A complexity is the four foot coal seam. The Hiawatha seam has 2% sulfur and is difficult to blend. The mine is now on temporary cessation so this proposal does not appear to be viable.
- -Pond #8 has been cleaned.
- -The cleaning of Pond #5 is well underway. The material is currently stacked within a portion of the pond. Mr. Pappas stated if they don't get the hoe repaired he would look to bring a contractor in to finish the work. The clean-out material is currently being stacked on the refuse pile. A portion of the clean out material has been taken to the refuse pile. The balance is still stacked in the refuse pile.
- -The mine site was covered with four feet of new snow. The snow came on Monday, March 6 and 8, 2000.
- -Mr. Cooper, Sunnyside Reclamation and Salvage, talked to mine officials about possibly purchasing the Star Point Mine. This is the same company that was involved with the Sunnyside Mine and many experiences. Co-Op is again interested in the Star Point property.

4A. HYDROLOGIC BALANCE: DIVERSIONS

There are approximately sixteen miles of constructed diversions within the disturbed and interfacing undisturbed area. This includes water conveyance systems of over 80 ditches and 32 culverts and berms that control and direct runoff. The diversions are designed and discussed in Section 742.300. All diversions were covered with snow.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

There are nine sediment ponds and three water impoundments. The sediment ponds provide sediment control for the majority of the disturbed areas. There are four BTCA's.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 3/9/2000

(Comments are Numbered to Correspond with Topics Listed Above)

The runoff from these areas are treated and controlled by alternative sediment control measures. The water impoundments are associated with the coal wash plant.

None of the sediment ponds were discharging during the inspection. Ponds 1,2,4,5,8, and 9 contained runoff; the remainder were dry. Pond inspections for the fourth quarter were on file at the mine site, including last year's annual inspection. As previously mentioned, the cleaning of Pond #5 is well underway. Pond #8 has just been cleaned.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Silt fences provide the sediment control on the BTCA areas. The mine has installed redundant sediment control measures including straw bales, silt fences, sumps, and check dams to retain sediment near the source.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The coal mine waste, as approved by the Division, covers an area of approximately 69 acres. The refuse pile approved design includes outslopes NTE 2:1, a MSHA berm, a sloping pile with positive drainage, diversions designed to meet 6 hr 100 year storm event, and commitment on restricting non-coal waste and combustible materials being stored in the refuse pile.

8. NONCOAL WASTE

The inspector sent a letter to the permittee on the non-coal waste, together with photos. The company was granted an extension on the submission of a plan until 2/11/99. The company has moved some vehicles to the parking area. Equipment has been marked with red paint indicating salvage, sell, or keep. This project is scheduled to be completed by the end of March.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

All roads, both ancillary and primary, are designed and discussed in the MRP. Most of the roads were muddy. The county road to #1 mine was not open because of recent snow storms.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM) Filed to: Price Field Office

Date: March 10, 2000

Inspector's Signature: My Knalenak #26

Wm. J. Malencik